To: McCoy, Erin[McCoy.Erin@epa.gov] From: Williams, Mike Sent: Fri 5/13/2016 5:58:00 PM Subject: FW: question about asbestos sampling - Des Moines TCE Erin, Here is Jeff Mitchell's response (ironically – he's in asbestos training today). Everything that is not wood, metal, plastic or glass is a suspect asbestos containing material and the only way to tell if it has asbestos is to take samples. Visually is not going to give you valuable info. From a financial stand point it will cost much more to go up twice (once for visual, then again to sample). It's terribly inefficient. Also when you factor in the cost of sample analysis (the labs we use charge us the labs), the most expensive thing is labor not the labs. I think John estimated 200 samples, so if we take that many it would cost [Ex. 4-CB] plus our contractallowed markup, so you're looking at roughly under [Ex. 4-CBI just taking a few samples really won't tell you much. We can reduce the number down to between 50 to 100 to save a little on costs and field time and that would still give him flexibility. What do you think? -Mike

Mike Williams | Sr. Project Manager/Hydrogeologist

415 Oak Street |Kansas City, Missouri 64106 | www.tetratech.com Direct: 816.412.1767 | Main: 816.412.1741 | Fax: 816.410.1748 | Mobile: 913.689.9367

Mike.Williams@tetratech.com

Tetra Tech | Complex World, Clear Solutions™

PLEASE NOTE: This message, including any attachments, may include privileged, confidential and/or inside information. Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.

